



TRACK INSPECTION REPORT

Name of track: **Stadium Marketa** _____ Type of track: **Speedway** _____

Location: **Prague** _____ Country: **Czech Republic** _____

Last Inspection: **2018** _____ Licence N°: **1125** Expiry Date : **2020** _____

DIMENSIONS:

Length of Track: **353m**

Length of Home straight: **70m**

Width of Home Straight: **10m**

Width of Back Straight: **10m**

Width of First Corner: **15.5m**

Width of Second Corner: **15.5m**

Comments on track shape : **Good Natural Shape for speedway racing** _____

SURFACING:

Material used for track base: **Coarse Gravel**

Material used for the surface: **Fine Gravel /Shale**

Surface depth: **250mm min.** Granulation: **0-4mm** Smooth surface: **Yes**

Drainage details: **Natural drainage on centre Green plus sump drains around inside edge of circuit with central water collection point under surface.**

SAFETY FENCE :

Fence height: **125cm** Kickboard height: **30cm**

Fence capping details: **Plastic tube**

Fence construction type: **Shatterproof plastic board on metal subframe suspended on springs covered by rubber tube for flexibility on impact.**

Width of slot for tapes: **12cm**

Kickboard height below slot: **30cm**

Boards painted: **Manufactured white plastic**

Details of any banners: **Standard SGP Velcro fixings**

Condition of fence: **Excellent, recently completely renewed**

Condition of kickboard: **Very good only minor abrasions**

The safety fences in Prague are a perfect example of a kinetic absorbing fences to be used in Track Racing.

INFIELD:

Height of inner edge: **Flat** Type of inner edge: **Concrete**
Marking of inner edge: **White Paint**
Full details of any obstacles in centre green and protection: **None Permanent Only Temporary collapsible SGP Advertising**

STARTING GATE:

Distance from 4th bend: **32m** Distance from 1st bend: **38m**
Details of protection: **Covered foam blocks**
Construction: **Metal Posts with electro magnet**
Number of sliders: **Two**
Marking of start line: **White Powder**
Distance of inner stanchion from track: **1.9 m**
Distance of outer stanchion from fence: **.9 m**

SIGNALLING:

Position of Green lights:
Position and number of Disqualification lights: **4**
Size and number of Disqualification flags/discs: **Number of Stop lights : 12 Around bends and along straights**
Condition of Stop Light Flexible Stanchions: **Not applicable – all of posts beyond 2 metre zone.**
Positioning of Amber warning lights: **In Pits and at Start Line**
Positioning of 2/3 minute warning siren: **In Pits**
Availability of 2/3 minute clock: **Yes for SGP**

NEUTRAL ZONE:

Distance to public barrier: **2m**
Obstacles – full details including protection in place: **Not applicable**
Observations / Recommendations: **None**

ADDITIONAL PROTECTIVE DEVICES:

APD Type and manufacturer/brand: **Briggo “ No Pain Barriers” A+**
Year of installation: **2021**

Comments on Triangle sections – condition/fixing/ID number:

Bend 1: **All good condition – no problems found**

Bend 2: **As Above**

Bend 3: **As Above**

Bend 4: **As Above**

Number of APD modules in Bend 1: **21**

Number of APD modules in Bend 2: **19+2 gates units**

Comments on APD modules – condition/fixing/ ID number/recommendations:
(Consider clips –velcro - upper and lower cables - fixing bolts – general damage)

Bend 1 - 4:

APD maintained in first class condition. All sections checked and found to be complete. Manufacturers Certificate available.

Comments on APD Kickboards :

Bend 1 - 4: **All APD Kickboards where found to be fully completed and correctly fixed in position**

Additional Protection - Exiting of Bends 2 and 4

Home straight Fence Type All fence now replaced with a new design so that is mounted and “floating” on flexible rubber tubing so as to absorb kinetic energy under impact. Fence comprises of shatterproof plastic board material mounted on a steel frame

Spare APD Modules

Number: **6 Full size + additional +1 small + 1 big units for the pit gates.**

Location: **On trailer in pit complex**

Condition: **Very good**

REFEREE'S FACILITIES:

Referee's box:

Position: **Above Start Line** Visibility: **Very Good.**

View of start line: **Very Good – Transparent panel improves visibility of gate 4.**

Security: **Room can be locked** Lighting: **Very Good**

Heating: **Available but not required** Clean: **Very clean and well presented.**

Privacy: **Referee and SGP Secretary only in room** Refreshment: **Available**

Switchboard:

Functioning of Green Light: **As per regulations**

Functioning of Disqualification Lights: **As Above**

Functioning of 2 minute Amber Lights: **As Above**

Functioning of 2/3/minute Siren: **As Above**

Number, location and condition of Toilets:

Men: **4 Blocks**

Women: **4 Blocks**

Disabled: **1 Additional temporary facilities hired in to cater for the large crowd.**

FIRST AID:

First Aid room as per 079.8.2: **Yes**

Doping test facilities: **Specific room with facilities available in tribune.**

Approach for ambulances to the track: **Pit gate onto the main road**

Distance to the nearest hospital: **3km 6 Minutes**

Hospital type: **Large General**

Fire extinguishers and tools: **All available – Full workshop facilities**

LIGHTS, SOUND AND POWER SUPPLY:

Location of light posts: **Around track behind neutral zone.** Number of light posts: **10**

Light output in kilowatts: - **2300 kW**

Light intensity on the track: **1200 Lux / 1800 Lux**

Light intensity in the pits: **1000 Lux**

Location of Loudspeakers: **On light standards**

Number of Loudspeakers: **24**

Maximum power supply capacity of the stadium in kilowatts: **Not Known kW**

Completely new high level floodlights system

TV BROADCASTING:

Location of Parking area for TV broadcasting trucks: **Layby adjacent to track entrance by the perimeter fence.**

Power supply for TV: **Some availability, TV company provide additional support.**

JURY ROOM:

Size and location: **72 sq metre Adjacent to pits complex**

Furnishing: **Chairs and tables for up to 50 people**

Facilities

Computer: **Yes**

Printer: **Yes**

Telephone: **At Stadium**

Internet: **Yes**

Wi/Fi: **Yes**

PRESS ROOM:

Size and location: **By entrance to main tribune very large suitable facility**

Facilities

Computer: **Yes**
Printer: **Yes**
Telephone: **At Stadium**
Internet: **Yes**
Wi/Fi: **Yes**
Other: **Full Kitchen facilities**

PRESS VIEWING AREAS

Location: **Main Tribune**

Suitability: **Very Good**

INSPECTOR'S RECOMMENDATION

Track is acceptable for speedway with 5 riders: **Yes**
Track is acceptable for long track with 5 riders: **Yes**
Track is acceptable for flat track with 12 riders: **Yes**

Track requires an additional inspection:

By the FMNR **No**

By the FIM **No**

If Yes please give details _____

Other Remarks or Recommendations: _____

Licence should be issued for: **3 years - 2023**

FIM Representative's name & signature:

Armando Castagna



FMN Representative's name & signature:

Petr Moravec



Club Representative's name & signature:

Pavel Ondrasik



Date: **16th July 2021**

The appointed track inspector must complete the track inspection report by computer and send it by e-mail to the FIM Administration, FMN concerned within a few days of the track Inspection. The original signed document must be sent by email afterwards to the FIM Administration with copies to the FMN and the Club concerned.